LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	corners in	, ,									
	Marquette	Located in:	Corner Code ##								
	(County)		·								
1.	Public Land Survey	<u> T R</u>									
		T R	,								
		T R									
		S 30 T 45N R 25	w 2,1,8.								
2.	Property Controlling										
	in Section	S T R						o =:+-	.	L	
3.	Miscellaneous	s T R		Register	of D	eeds 5	tamp	& File	Num	per	
	Property in Sec.	S T R			-						
4.	Lot No	, Recorded Plat		<u> </u>	В	C D	E F	G H	1 J	K L	. м
5.	Private Claims			—— <u>"</u> [l <u>l</u>	<u> </u>	L-\-			┨┛
				3	Ĭ	ľĬ	ΙĨ	lĭ	lĬ		ĹЫ
								$\Box \Box$	\sqcap		
				4⊦	- לְ	B	- 9	10-	 -''	+	12-
1	David Babbitt	_ , in a field survey on	10/11	: 5⊢	+-	╂╌┼╼	 	 	╂╾┼		\vdash
do	harabu cartifu that under i	requirements of P.A. 74. MiChiga	n P.A. of 1970, the corner points memories	¹ 6⊢	_1B	17	1/6-	15	 	╼╁─╴	(3
in l	ines 1 and 2 above were	in conformance with regulation	ons and rules therefore as required in the Department of the Interior, Bureau of Land	ā , L		I	├	- - 	1-1-		╂╾┤
14-		of a Court of Law and/or that the	COMPT POINTS MONTIONED IN TIMES 3, 4 BING	° ₽∟	-18	20-	1-21-	J22-	23		24-
-h	we were in conformance	with the rules of the Michigan B	oard of Land Surveyors of by a Decree of	اه ه				<u> </u>	\perp		$oxed{oldsymbol{oldsymbol{\sqcup}}}$
Co	urt of Law; established	, re-established, monumented	l, re-monumented, recovered, found a	s 10	_30	29_	-28-	 27-			إ
	pressed below:				—30 	1—29— 1	1	T-1'-	Τί		1
NO	TE: Not more than 4	l corners, all in the same to	wn and range, may be recorded	11 -	_	1-1-	 -		11	\neg	
	on this certifica			12	−31 —	 3 2—	 3 3-	34	- 3 5		36-
				13 L		↓	I l				4
A.	Description of origin	al monument and accessorie	es and/or subsequent restoration:								
_			. No previous record.								
2	. E I/Ib corne	r n. line section so	. No previous record.								
			No amendana magard								
1	. W 1/16 corne	r n. line Section 30). No previous record.								
		- 41									
3	. W 1/16 cor.	on E-W 1/4 line Sec	tion 30. No previous rec	ora.							
B.	Description of corne	r evidence found and/or me	thod applied in restoring or reestabli	shing corn	er:						
					. e (2	^			
2	. Set MPOL bet	ween the north $1/4$ \circ	corner and the NE section	corner	or :	secti	יכ חס	υ.			
								. 1			
1	. Set by singl	e proportion to the	GLO record between the no	orth 1/4	COL	rner	and	the			
	NW section c	orner of Section 30	•								
8	. Set by singl	e proportion to the	GLO record between the ce	enter of	sec	ction	and	the			
	west 1/4 cor	ner of Section 30.	Found other irons (proper	ty corn	ers	?) ir	the	vici	nit	У	
	but not of r	ecord. This section	nhas a number of markers o	of vario	us c	descr	ipti	ons			
	annarently n	ot set by proper se	ction subdivision methods.	,							
	аррателету п	or 300 s, proper se									
				•							
C	Description of many	ment for corner and access	ories established to perpetuate locat	ing the pos	sition	of the	corne	er:			
	-				8.		Monu				
	2. DNR Monument							N68E	25	. 65	
N	W cor. garage S		2" w.pine, N50E, 39.9"								
	SW cor. house S1	· - •	"w.birch, S44E, 25.0"					\$50E			
	4" w.pine, S87W	•	2" w.pine, \$70W, 19.5"					\$28W			
	4" spruce, N47W	1, 28.0' 8	" hard maple, N61W, 15.7"		10"	w.pi	ne,	N5 I W	, jl	.15	•
					•						
)									
	/ / /	wit B. Bal	212		,	00					
e:	anad by (N/2	vil 15- 1150 1	CALLY Date	1-2	<u> </u>	87					
ال	grieu uy		Date		_				_		

Surveyor's Michigan License No. 21558

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983