## LAND CORNER RECORDATION CERTIFICATE

For corners in		Fi	)							
	Marquette (County)	Located	ln:	Corner Code ##						
	Public Land Survey  Property Controlling	т т	R R R R N R 25W	6, 5, 4.	- -					
	in Section	S T	_ R		_					
3.	Miscellaneous Property in Sec.	S T			1 114	gister of De	eds Stamp	& File N	umber	r
	Lot No,					- A B C	DEF	G H I	JK	L M
					<del></del>	2 6 6 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	- 5	<b>┼</b> ─┇╾┼	-2	-{-
do l in I cur Mai abo Cou exp	David B. Babbit: hereby certify that under rines 1 and 2 above were rent manual of survey inshagement or by a decree over were in conformance view were in conformance view of Law; established, pressed below:  TE: Not more than 4	equirements of P.A. 74, in conformance with a tructions of the United of a Court of Law and/or with the rules of the Micre-established, monucorners, all in the secondary.	Michigan P.A. of regulations and States Departm that the corner particular chigan Board of Lumented, re-mo	1970, the corner points rules therefore as requent of the Interior, Bure soints mentioned in line and Surveyors or by a linumented, recovered,	mentioned nired in the nau of Land s 3, 4 and 5 Decree of a found as	4 7 6 18 19 10 30 11	- 8 - 9 - 17 - 16 20 21 29 - 28	15   -22   -27   -2	-14	-132425
	on this certificate	<b>.</b>				18 3'1-	32 33	34	35	36-
A.	Description of origins	i monument and acc	essories and/	or subsequent restor	ation:					
6.	NE 1/16 come:	r of Section 30	). No pre	vious record.						
5.	N 1/16 corner	on N-S 1/4 lin	ne of Sect	ion 30. No pre	evious rec	ord.				
4.	NW 1/16 come	r of Section 30	). No pre	vious record.						
в. 6.	Description of corner Set at the cor	evidence found and		· _	-	corner:				
5.	Set MPOL betwe	en the center	of Section	n 30 and the N	1/4 come	r of Sec	tion 30.			
4.	Set at the con	mputed center o	of the NW 1	L/4 of Section	30.					
^	Description of manuscription					isi	f the garage			
6. 6" 6"	Description of monument.  Spruce, N38E, Sw.pine, S11W, S71W, r.pine, S71W, r.oak, N11W, 42	52.2' 106.6' 114.6'	5. DNR M 14" w.pir 8" r.pine 8" spruce		4. 9" w 8" s 7" s	position of DNR Monu pine, S. pruce, N. pruce, N.	ment 58W, 9.2 77W, 9.1 58E, 26.	' ' 95'		
_	ned by		a l b l s 21558			26-	89			

Surveyor's Michigan License No. \_\_\_\_\_

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1963