MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

1999 DEC 22 AM 11: 23

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

4	· ·	R RECORDATION CERTIFIC	· · · · -	- 10111 20
	Filing Require	ment of Act 74, Mich. P.A. 1	970	sin A. Manley
For corners in		1	Fate	cin a. March
<u> MARQUETTE</u>	Located In:	Corner Code #	PEDI	STED OF OFFICE
(County)		•	· 'KE JUST'	SIGN OF DEEDS OF
				*
Public Land Survey	T <u>45N</u> R <u>25W</u>	A-5 🗸		
·	T 45N R 26W	M-5		
	TR			
	TR	 		
2. Property Controlling S_	T R			
in Section S	TR			
3. Miscellaneous S	T R			R 2 PAGE 184
Property in Sec. S_	T R	-	LIBER	ILC PAGE 104
Troperty in Sec. 3_			Destates of Decide	Otania o File Manuface
		<u></u>	Register of Deeds	Stamp & File Number
4. Lot No, Record	ed Plat			
5. Private Claims				
		· · · · · · · · · · · · · · · · · · ·	ABCDEF	GHIJKLM
			-	
			2 6 5 4 -	
			3	
I, GERALD W. CARLSON	, in a field survey onC	OCTOBER, 27th , 19 99 , do		
hereby state that under requireme	ints of P.A. 74, Michigan F	P.A. of 1970, the corner points	4 7 8 9-	10 11 12
mentioned in lines 1 and 2 above	were in conformance with r	regulations and rules therefore as	5	
required in the current manual of sur	vey instructions of the United	States Department of the Interior,		
Bureau of Land Management or b			6 -18 17 16	15 14 13
mentioned in lines 3, 4 and 5 above			7	
Land Surveyors or by a Decree o				
recovered, found as expressed belov		ed, re-established, thoridifferited,	8 -19 -20 -21	22-1-2324
1900vered, Todina as expressed belov	¥•		9	
NOTE: Not are a three or a second		1 1		
	rs, all in the same town and	range, may be recorded	10-30-29-28	27 26 25
on this certificate.			11	
			12 31 32 33	34 35 36
A. Description of original monu	ment and accessories and/	or subsequent restoration:	12 31 32 33	73-73
A-5: Corner common to Section			13	
26W.				
1844: William A. Burt's original	township houndary survey	notes describe the corner	RATIFIED BY PEE	en choup
monument as a wood post refere			RATIFIED BY PER	in Ghooi-
	1L 14" Y. Birc	h N14W, 19L	P.A. 345 OF 1990	2.
11 11 511011 0142, 1	14 1.500	11 141-444, ISE	Lang I	Queson
(SEE REVERSE SIDE)			101	25/99
(OLE REVERSE SIDE)			DATE	- free free free free free free free fre
B. Description of corner evidence	ce found and/or method ap	plied in restoring or reestablishi	na corner:	
A-5: 1999: No original corner ev	idence found. Found and re	elected a 3 3/4" aluminum table	t on a 1 1/4" outside di	ameter iron pipe
protruding 0.7' above ground. T				
corner two miles North and the s				
		- -		
of it's intended location. We ree			surement between the s	ection corners one
mile North and one mile South.	Distances North and South	2642.64*.		
Checked Line Call: South, 8 chair			•	-
Checked Line Call: North, 19.63				e South bank of river.
Checked Line Call: East, 1.14 ch				
Checked Line Call: West, 0.50 cl	hains (33'), Descend 50 fe	et C. N.W Measured 100' (1 o	chain long).	
C. Description of monument for	r corner and accessories es	tablished to perpetuate locating	the position of the corr	ner:
A-5: 1999: Removed the existing				
to identify the corner Monument			,	
	5.68' (Sackett-NBT)	7" Maple	N82E, 14.30'	
	0.60'	6" Twin Maple	S04E, 13.38'	
O Maple 30244, 3	0.00	o iwni wapie	304E, 13.30	•
Green Steel Sign Boot out Valley	Summer Morters Store	N117W . 9 141		
Green Steel Sign Post w/ Yellow		N17W, 3.14'		
Note: Bearing trees have painted		azes, a.n. measuring nais, and	stamped 5.1. tags attix	.eu.
	ch Report 99100	_		
BK 12, Pg. 128				

Surveyor's Michigan License No.___

Date 12-8-99



1 0 2000

A-5:

PART A CONTINUED:

SECTION

1852: Martin M. Hall's original subdivision survey notes describe the corner as a post and add the following reference:

N62E,

1852: Martin M. Hall's original subdivision survey of T45N-R26W notes describe the monument as a post and add the following reference: 12" Sugar

S56W.

1950: Department of Conservation survey notes indicate a set corner 72 links West of the 80 chain marker and established the following references:

Red Oak NO7W, 42 L 5" S40E,

S. Maple

No Date: In the Marquette County Road Commission field book 643 the corner is indicated as a 1" iron pipe and brass cap set by the Conservation Department on the 24th of August 1950. It is noted that the corner was set from an old B.T. and probable line tree 9 chains West.

1989: A Survey Sketch by Sundberg, Carlson and Associates, Inc., indicates the Southwest corner distance S88-58-49E, 5128.73 to the Southeast corner of Section 7. No description or accessories given.

1991: An LCRC by Keith Sackett, P.S. #19006, Liber 5 RC, Pg. 309 indicates that he searched for the monument and accessories set by Dean Delameter in 1950 and did not find them. Sackett restored the corner position by single proportionate measurement between the section corner one mile South and the Township corner two miles North. He set a DNR monument and established the following references:

Red Oak

NO3E.

25.31

Red Maple 5"

N83E.

14.0

5" Sugar S04E,

13.2

5"

S75E,

S81W,

30.45

Squared Maple

0.9