SURVEY & REMONUMENTATION

| MARQUETTE COUNTY |
|---------------------|
| RECEIVED FOR RECOPD |
| AN LOW WEDDING |

APR 2 8 1995

Surveyor's Michigan License No. 39091

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1994 DEC 29 PN 1:54

| Marquette COMMISS | SION Located In: | Corner Code ≠ | 1 | Patric | TER OF DEIDS O | |
|---|-------------------------------|---------------------------------|---------------------------------|---|--|--|
| (County) | cocated iii, | Comer Code 44 | DATIFIED - | | | |
| 1. Public Land Survey | T 46N R 25W T 45N R 25W | J-13 √J-1) √ | P.A. 345 OF | P.A. 345 OF 1990 | | |
| · · | Γ Ř | | 1 // | Busame | Application and the second | |
| Property Controlling S | T R T R | | DATE 🔾 | T12,1994 | į | |
| in Section S | T R | | | LINEN | 1 1 200 200 | |
| | T R T R | | Register | of Deeds Stamp | 1 PAGE 208 | |
| | | | <u> </u> | | | |
| 4. Lot No, Record | led Plat | | | B C. D E F | GHIJKL | |
| | | - | 2 | - | | |
| Michael Mileski | | 0 | 3 - | - | + | |
| I, Michael Mileski in a do hereby certify that under requirement | field survey on | September 1994 | | - - - | | |
| in lines 1 and 2 above were in confo | ormance with regulations a | and rules therefore as required | tin the the | -18-17-16- | 14-13- | |
| current manual of survey instructions Management or by a decree of a Court | t of Law and/or that the corn | er points mentioned in lines 3. | 4 and 5 | | | |
| above were in conformance with the r Court of Law; established, re-estat | rules of the Michigan Board | of Land Surveyors or by a Dec | ree of a | 20 - 21 - | 22 - 23 - 24 | |
| expressed below: | • | | 10 | 30 29 28 | 27 26 25 | |
| NOTE: Not more than 4 corners on this certificate. | , all in the same town a | nd range, may be recorde | , | ++++ | | |
| on uns ceruficate. | • | • | 12 | -3 ¹ 13 ¹ 23 ¹ 3 | 34 35 36 | |
| A. Description of original monun | nent and accessories an | nd/or subsequent restoration | ก: | ··· | - | |
| J-13; South One-Quarte | r Corner Section 35 | ; | | TE OF MI | CL. | |
| See back of form. | | | | 16/ | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | |
| | | | | ★ MICHAEI ★ MILESI | | |
| • | • | | | PROFESSIO | ONAL K | |
| | | | | SURVEY! | OR O | |
| | | | | 39091 | est de | |
| B. Description of corner evidence | e found and/or method | applied in restoring or rees | tablishing corne | | CHALL | |
| J-13; South One-Quarte | r Corner Section 35 | ; | | | | |
| Reestablished the | south one-quarter | corner of section 35 | at proportio | nate distance | along an arc | |
| Commedany me so | ameast comer or st | ection 36 and the sout | | | ition 34. | |
| | | State Plane | Coordinates - NAD 83 | <u>:</u> | | |
| | | Zone Numl | oer - 2111 Mi | chigan North | | |
| 4 | | Units | Internation | onal Feet | | |
| | | X | = 565310 = 261460 | 6.71018 362.34501 | | |
| | | | ~ Z0140. | 302.34501 | | |
| Description of monument for c | corner and accessories e | established to perpetuate to | ocating the posit | ion of the corner: | : | |
| J-13; South One-Quarter | | | , | | | |
| | | | | | | |
| to location. | normium pipe with | 3" aluminum cap (Ber | ntsen A1NB3 | O) appropriate | ely stamped as | |
| Set ½ "x18" iron ro | od & cap #39091 | N45°E | 45.00' | | | |
| * Set ½ "x18" iron ro | od & cap #39091 | S45°E | 45.00' | | | |
| Set 1/4 "x18" iron re | od & cap #39091 | S45°W | 45.00' | | | |
| Set ½"x18" iron ro Location Post | oa & cap #39091 | N45°W North | 45.00' | | | |
| 11. | ill. | NOLLI | 1.5' | ` ` ^ | a | |
| lancoul land by | whether | Date | Z/ / | 600 / W | 194 | |