1999

٠.	٠.		· c	2 4.0	~~~

 MARGHETTE COUNTY 	
THOMIGAN	
RECEIVED FOR RECOR	ľ

SECTION		IER RECORDAT irement of Act 7	11111 1111 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
For corners in MARQUETTE (County)	Located In:	Corner (Code #	REGISTER OF DEEDS OF	
1. Public Land Survey	T <u>45N</u> R <u>25W</u> T <u>44N</u> R <u>25W</u> TR TR	<u>K-13</u> <u>K-1</u>	<u>-</u>		
2. Property Controlling S_ in Section S_ 3. Miscellaneous S_ Property in Sec. S_	T R R T R T R T R T R T R T R T R T R T			Liber ${f R2}$ PAGE $$	
4. Lot No, Record 5. Private Claims	ed Plat			ABCDEFGHIJKL	
on this certificate. A. Description of original monumers. K-13: Corner common to Section R25W. 1844: William A. Burt's original spost referenced by:	ments of P.A. 74, Michigative in conformance with very instructions of the Unity a decree of a Court of a were in conformance with a Court of Law; established a court of Law; established and a coessories and a sand 36,T45N-R25	an P.A. of 1970, the regulations and red States Department Law and/or that the the rules of the Mished, re-established and range, may be and/or subsequent to the subsequent of the subsequent o	the corner points ules therefore as ent of the Interior, he corner points lichigan Board of d, monumented, e recorded restoration: 1 and 2, T44N- nt as a wood	3 4 7 8 9 10 11 12 5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 RATHED BY PEER GROUP P.A. 345 OF 1990 Acry & Bresser DATE Nov 2, 1998	
	bdivision survey notes f 7 L 14" Tam		escribe the come 32 L	pr monument as a wood post referenced by:	
_ ·	ast 1/4 Corner of Section	·		corner from bearing trees in T45N-R25W. South 1/4 Corner of Section 35. No	
1910: The corner is indicated on accessories given.	a mining map filed by J	loseph Primeau, R	egister of Deeds	. No description of corner monument or	
	of Section 35, and a Dis	tance West of 26	40' to the South	erton in 1968, indicates a Distance North of 1/4 Corner of Section 35. An interior angle of given.	
condition. Corner was found $\pm i$ -very well with those recorded in	vidence found. Found ar 850' East of 2-track ro L. 5, RC Pg. 39. Checke ourse N-S. Checked Line	nd accepted a 2" ad along old E-W ed Line Call:(Leave e Call: (Leave Tan	O.D. Iron Pipe in brush line. Beari e Swamp Course narack Swamp N	swamp, 1.5' above ground, in very goodings and distances to found references check N-S, West 2.50 chains [165']). Measured I.E., 5.00 chains [330'] North from Corner).	
C. Description of monument for				g the position of the corner:	

found 2" O.D. Iron Pipe. Monument is 1.5' above ground. Referenced by found d.h. nails with washers in existing witnesses: 20" W. Pine(scribed) N20E, 63.33' (Carlson NBT) 7" Spruce (dead) S85W, 59.02' (Carlson NBT) 8" Spruce (dead) S41W, 50.47' (Carlson NBT) 11" Cedar (scribed) N10W, 58.96' (Carlson NBT)

Established new references:

6" Spruce

N64E, 30.76'

5" Cedar

N26W, 23.05

Green Steel Sign Post w/ Yellow Survey Marker Sign N08W, 2.00

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

Surveyor's Michigan License No._

24589

E OF MICH

GERALD W.

CARLSON SURVEYOR No.

W. ... E S 1890

K-13;

PART A CONTINUED: SECTION

1962: A Michigan Department of Conservation Land Corner Record by Amie A. Metsa, not recorded, indicates the corner as a 2" Iron Pipe w/ coupling attached to end. This corner was set from original tamarack B.T.'s probably by mining company surveyors apparently 40 to 50 years ago. Set new bearing trees after checking the pipe for accuracy with the original B.T's. The Tamarack 14 S81E 32 links was a 4-foot shattered stub, but had both faces plain and scribe marks very distinct on upper face. The other tamarack B.T's were low, rounded atumps with all evidence of scribe marks and faces gone. All B.T.'s, however, checked well for bearing and distances to pipe. Left pipe in exact location found. Referenced by:

6" Black Spruce

¹S48W,

35.5 L

10" Cedar

14" W. Pine

S17E.

95.0 L

1982: A Certificate of Survey by Gerald W. Carlson P.S. #24589 for the Minatome Corporation (No Liber or page given), indicates the corner as a monumented corner. Distance N89-27'-15"E, 2638.63' to the South 1/4 Corner of Section 36. Distance S89-14'-58"W, 2637.97 to the South 1/4 Corner of Section 35. No accessories given.

1982: An LCRC recorded by Gerald W. Carlson P.S. #24589 in L. 5, RC Pg. 39, indicates a found 2" Iron Pipe, 2' high, and a 6" square Cedar Post in swamp. Referenced by:

18" W. Pine 8" Spruce

N18E. S43W, 63.25' (Scribed)

50.55

7" Spruce

S86W,

59.10

11" Cedar

N13W.

58.85' (Scribed)