SUPERIOR RECO-SE VITON

HER L 9 1999

SECTION

Surveyor's Michigan License No. 24589

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

MARQUELLE COUNTY THUMBAR RECEIVED FOR RECORD

1998 DEC 16 PM 3: 20

	Filing Require	ment of Act 74, Mich. P.A. 1	970	NAME OF TO THE OF	20
For corners in MARQUETTE	Located In:	Corner Code #		Patricis a. Mank	p 211.
(County) 1. Public Land Survey	T 45N R 25W	D/E - 13 M.C. #5		REGISTER OF DEEDS	du
2. Property Controlling in Section 3. Miscellaneous Property in Sec.	T 44N R 25W T R T R S T R S T R S T R S T R S T R	_D/E - 1 M.C. #7	Regist	LIBER ${f R}^2$ PAGE or of Deeds Stamp & File	
4. Lot No, Rec	orded Plat	L.			
5. Private Claims			АВО	DEFGHIJ	ĸ
do hereby state that under req mentioned in lines 1 and 2 abd required in the current manual of Bureau of Land Management of mentioned in lines 3, 4 and 5 al	uirements of P.A. 74, Michigan ove were in conformance with resurvey instructions of the United or by a decree of a Court of Lapove were in conformance with the of a Court of Law; establish	MAY 5 TH , 19 98 , P.A. of 1970, the corner points egulations and rules therefore as States Department of the Interior, w and/or that the corner points he rules of the Michigan Board of ed, re-established, monumented,	1 2 - 5 - 3 4 - 7 - 5 6 - 18 - 7 8 - 19 -	-5 -4 -3 -2 -8 -9 -10 -11 -17 -16 -15 -14 -20 -21 -22 -23	
NOTE: Not more than 2 cor on this certificate.	rners, all in the same town and	I range, may be recorded	9 10—30—	29 28 27 26	+
A. Description of original mo D/E-13: <u>Meander Corner com</u>	onument and accessories and/omon to Section 32, T45N-R25	or subsequent restoration: W and Section 5, T44N-R25W	11 12 31	32333435	<u> </u>
1844: William A. Burt's origin Cedar on West side of Escana 12" Cedar N74W,	nal survey notes describe the c aba River. Referenced by: 24 L	orner monument as a 16"			
No Date: M.C.R.C. Governme Department of Conservation I 20" Cedar S04E, 4" S. Maple N27W,	Brass Cap (7/18/50) on West s 37 L 16" Balsam	ion 5, T44N-R25W, indicates t side of Escanaba River. Referen S21W, 04 L	he corner as a ced by:	1" Iron Pipe and Michiga	ıņ
Escanaba River on North side Corner was located by District	of Section 5, T44N-R25W, it to Forester Metsa, of Gwinn.	Record, no name given, indicate also indicates the corner monu When I saw the Corner, one of This corner was set on July 18 S21W, 4 L	ment as a 1" li the original B.1	ron Pipe w/ 4" Brass Cap T.'s, a cedar was still plai) .
D/E-13: 1998: No original corcap, stamped to identify the o	mer evidence found. Found and corner. Pipe was leaning East,	plied in restoring or reestablishi d accepted a 1 1/2" O.D. Iron f 1.0' high. Bearings and distance stance East is 217.89. Distance	Pipe with 4" di ses to remainin	g 2 references checked v	atio: /ery
D/E-13: 1998: Reset monume	ent in a vertical position using	tablished to perpetuate locating recorded bearings and distance und. Measured to fd. d.h. nails 23" Cedar	s from 2 remai and washers i	ining witnesses. Stamped	ł
23" Hemlock S57W,	43.61'	12" Maple	N07W, 11	.28'	
Green Steel Sign Post w/ Yell	ow Survey Marker Sign S48	BW, 5.10'		and the	
Note: Bearing trees have pain and stamped B.T. Tags affixe	ted face, butt, and side nail bl d.	azes, d.h. measuring nails,	É.	GERALD W.	À
		P.A. 345 OF 1990 Aarry Buss DATE NOV 2, 1998		CARLSON SURVEYOR No. 24589	STATE OF THE PARTY
Signed by Lusti	w Caleon	Date	498	To land the same of the same o	

REMOVED WELL MINDEY.

WAR L & 1999

D/E - 13 M.C.: PART A CONTINUED:

SECTION

1982: A Certificate of Survey by Gerald W. Carlson P.S. #24589 for the Minatome Corporation (No Liber and page given) indicates the corner as a monumented meander corner on the West side of the Escanaba River. Distance N89-28'-34"E, 217.80' to the S.E. Corner of Section 32;, Distance S89-28'-34"W, 2419.56' to the South 1/4 Corner of Section 32. No accessories given.

1982: An LCRC recorded by Gerald W. Carlson P.S. #24589 in L. 5, RC Pg. 38, indicates that the corner was a D.N.R. Monument set by Dean DeLamater on 7/18/50. Recorded references:

20" Cedar

S04E.

37 L

16"

Baisam

S21W,

04 L

4" S. Maple Carlson found an Iron Pipe w/aluminum cap, +/- 9' West of river, and Cedar stump at correct bearing and distance for Cedar B.T.. He set a 2"X2"X4'

N27W,

15 L

6" Maple (in cluster)

N20W.

9.90

12" Cedar 8" Balsam N88W, S40E.

stake alongside pipe. Referenced by:

36.05 24.46

ı,

20" Cedar

S03E,

25.85' (DeLamater NBT)

1983: A Certificate of Survey recorded by Gerald W. Carlson P.S.#24589 in L. 001, SM pp. 440, 441, and 443 indicates the corner as a fd. DNR Monument and remains of Cedar stump at correct bearing and distance for original Cedar B.T.. Referenced by:

12" Cedar

N88W,

36.05

6" Maple (in cluster)
20" Cedar

N20W, SO3E,

9.901

8" Balsam

S40E.

24.46

25.85' (DeLamater NBT)