MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_45. NR_46_#-

			MarquetteCOUNTY
DESCRIPTION	OF	CORNER	_Section Corner common to Sections 7,8,17,18
DESCRIPTION	OF	CORNER	MONUMENT_1"_Pipe_with_4"_Brass_cap
WIT TNESSES	то	CORNER	20% Red Pine = 8 76 W == 113 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established, by double proportionate measurement, by Ferestry Division survey crew, while making a partial resurvey of this area. Area badly burned. One possible original B.T., badly rotted.

Corner was placed and witnessed April 27, 1953.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 11/30/59