## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_45 NR\_26 F.

			Marquette COUNTY
DESCRIPTION	OF	CORNER	Meander Corner on N. side of Pasa Lake between Sections 29 & 30
DESCRIPTION	OF	CORNER	MONUMENT_1# Pipe
WIT TNESSES	то	CORNER	5" Ceder-~ 8.62 E - 30 Links
			10° W. Birch = N 6 W = 19 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Corner had previously been located and perpetuated by unknown surveyor. One original B.T. in place, in fair condition.

Corner was rewitnessed October 23, 1951.

SURVEYORS SEAL

SIGNED SIGNED LAND SURVEYOR DATE 11/1/51-