## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_45. NR \_-26 - W-

			Marquette COUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sections 21 & 22
DESCRIPTION	OF	CORNER	MONUMENT_1# Pipe with 4# Brass cap
WIT TNESSES	то	CORNER	_10#_Cedar_ = H 20_E = 50. Links
			_12# Cedar - H 66 M - 75 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while working in this area. Two original B.T.'s in place, in poor condition.

Corner was placed and witnessed August 9, 1951.

SURVEYORS SEAL

SIGNED SEAU C. SIJA MATU DATE 8/23/51.