## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_45 NR\_26\_W\_ T 45 NR 27 W

			Margiero COUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sections 31 & 36
DESCRIPTION	OF	CORNER	MONUMENT 1" Pipe with 4" Brass cap
WIT TNESSES	то	CORNER	10" Cedar - 8 45 W - 16 Links
			10" Gedar - N 58 E - 29 Links
			10" Geder - 5.46 F = 39 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division Survey crew, while working in this area. Both original P.T.'s in place. Definitely an original corner Corner was placed and witnessed October 25, 1950.

SURVEYORS SEAL

SIGNED Skam l. Desemble DATE 1/15/51 PREGISTERED LAND SURVEYOR