MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T.45 NR.26 W.

			MarquetteCOUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between sections 14 and 23.
DESCRIPTION	OF	CORNER	MONUMENT 2" Pipe with Brass plug
WITTNESSES	то	CORNER	6* Spruce - S 87 W - 72 Links
			6* Spruce - S 50 W - 30 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner was found by Forestry Division Survey crew while running Random line across Township. Corner had been set by C.C.I. Surveyors. Both original B.T.'s still in place and in excellent condition. Corner was found and witnessed August 22, 1950. Definitely an original corner.

SURVEYORS SEAL

SIGNED Stan C. Sie Mater DATE 9/20/50 _