## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 45 NR 26 W.

			marquetteCOUNTY
DESCRIPTION	OF	CORNER	1/4 Corner between Sections 13 and 14
DESCRIPTION	OF	CORNER	MONUMENT 2" Iron pipe with Brass plus
WIT TNESSES	то	CORNER	10" Hemlock - M & W - 24 Links
			12" S. Maple - S 14 E - 78 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was located by District Forester Metsa, of Gwinn. Had been previously set by C.C.I. Surveyors. Could not satisfy myself that the original B.T.'s were there, so we ran Transit lines, and by proportionate measurement proved corner to be in the proper location.

Corner was witnessed on August 22, 1950.

SURVEYOR'S SEAL

SIGNED SLAW C. SESTIMATE DATE 9/20/50