MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD

1999 DEC 22 AM 11: 23

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1. Public Land Survey T 45N R 25W	SECTI	ON Filing Require	ment of Act 74, Mich. P.A. 1	1970 Dti. ola 1.
T. 45N R. 26W T. R. 2. Property Controlling S. T. R. In Section S. T. R. Property in Sec. S. T. R. 4. Lot No. Recorded Plat S. Private Claims 4. Lot No. Recorded Plat S. Private Claims 4. Lot No. Recorded Plat S. Private Claims 1. GEPALD W. CARLSON In a field survey on May 21st I. 19 99, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in fine 1 and 2 above were in conformance with requirement and uses therefore as required in the current manual of survey insurcions of the United States Department of the Intracks, Bureau of Land Management for by a decree of a Court of Law and/or that the conner points mentioned in fines 3, 4 and 5 above were in conformance with the regulations and rules therefore as recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Bacciption of original menument and accessories and/or subsequent restoration: A.2. Quarter corner common to Section 6, T45N-R25W and Section 1, T45N-R25W, I. 12* Maple N. 36E, 29L 1999-1913. Charles Currmings* notes inclicate that he determined the quarter corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of		Located In:	Corner Code #	Patricia d. Monlay REGISTER OF DEEDS
2. Property Controlling S T R R S Miscellanous S T R R R S Miscellanous S T R R R R Register of Deeds Stamp & File Number R 2 PAGE 181 4. Lot No. Recorded Plat F. Private Claims R Register of Deeds Stamp & File Number R R R R R R R R R R R R R R R R R R R	1. Public Land Survey	T <u>45N</u> R <u>26W</u> TR	A-2 M-2	
4. Lot No	in Section 3. Miscellaneous	S TR		LIBER R2 PAGE 181
5. Private Claims 1. GEPALD W. CARLSON , in a field survey on May 21st 19 99 , do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in line 21 and 2 above were in conformance with requirement and rules therefore as required in the current manual of survey instructions of the United States Department of the Michigan Board of Land Surveyors of by a Decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors of by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of enginal monument and accessories and/or subsequent restoration: A.2. Quarter corner common to Section 6, T45N-R26W and Section 1, T45N-R26W. RAYLEDGE Common Points in the Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions settling the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions settling the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions settling the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions settling to corner. (SEE REVERSE SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. (SEE REVERSE SIDE) B. Description of corner evidence found, Pound and accepted a 1 1/4" O.D. Pipe with 4" diameter Michigan Department of Natur. Resources Aluminum Tablet O.6" above ground. Pipe is painted orange. Chacked Line Call: South, 13.1 chains (884.6). Stream 4 links (2.60), course-West. With a hip chain we measured 907' South to the contentine of a 5f wide stream. Distance North is 2705.66° and South is 2617.80'. C. Description of monument for corner and accessories establis	4. Lot No. Rece	orded Plat		103000101000000000000000000000000000000
I. GERALD W. CARLSON in a field survey on May 21st 19.99 do hereby state that under requirements of PA. 74. Michigan PA. of 1970, the comer points montioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Intestor, Bureau of Land Managament or by a decree of a Court of Law and/or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, and/or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: A-2: Quarter corner common to Section 6, T45N-R25W and Section 1, T45N-R26W. 1844: William A. Burt's original Township boundary survey notes describe the corner monument as a wood post referenced by: 10' Spruce S85W, 31L 12' Maple N36E, 29L 1909-1913: Charles Cummings' notes indicate that he determined the quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing the corner. Northwest corner of Section 6 and S00-20-00W, 2635' to the Southwest corner of Section 8. He does not mention setting or references given. His notes indicate the quarter corner owold be located a distance NG0-20-00CE, 2723-22' to thorthwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing of the corner. A-2: 1999: No original corner evidence found. Found and accepted				ABCDEFGHIJKLM
I. GERALD W. CARLSON in a field survey on May 21st 19.99 do hereby state that under requirements of PA. 74. Michigan PA. of 1970, the comer points montioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Intestor, Bureau of Land Managament or by a decree of a Court of Law and/or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, and/or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: A-2: Quarter corner common to Section 6, T45N-R25W and Section 1, T45N-R26W. 1844: William A. Burt's original Township boundary survey notes describe the corner monument as a wood post referenced by: 10' Spruce S85W, 31L 12' Maple N36E, 29L 1909-1913: Charles Cummings' notes indicate that he determined the quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing the corner. Northwest corner of Section 6 and S00-20-00W, 2635' to the Southwest corner of Section 8. He does not mention setting or references given. His notes indicate the quarter corner owold be located a distance NG0-20-00CE, 2723-22' to thorthwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing of the corner. A-2: 1999: No original corner evidence found. Found and accepted				1
I. GERALD W. CARLSON in a field survey on May 21st 19.99 do hereby state that under requirements of PA. 74. Michigan PA. of 1970, the comer points montioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Intestor, Bureau of Land Managament or by a decree of a Court of Law and/or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, and/or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: A-2: Quarter corner common to Section 6, T45N-R25W and Section 1, T45N-R26W. 1844: William A. Burt's original Township boundary survey notes describe the corner monument as a wood post referenced by: 10' Spruce S85W, 31L 12' Maple N36E, 29L 1909-1913: Charles Cummings' notes indicate that he determined the quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing the corner. Northwest corner of Section 6 and S00-20-00W, 2635' to the Southwest corner of Section 8. He does not mention setting or references given. His notes indicate the quarter corner owold be located a distance NG0-20-00CE, 2723-22' to thorthwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing of the corner. A-2: 1999: No original corner evidence found. Found and accepted				
hereby state that under requirements of P.A. A, Mindingal P.A. of 19/0, the corner point mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Elwa and/or that the comer points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: A-2: Quarter corner common to Section 6, T45N-R25W and Section 1, T45N-R26W, 1844: William A. Burt's original township boundary survey notes describe the corner monument as a wood post referenced by: 10° Spruce S85W, 31L 12" Maple N36E, 29L 1909-1913: Charles Cummings' notes indicate that he determined the quarter corner location by pro-reting his distance between the Northwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing trees. No description or references given, His notes indicate the quarter corner would be located a distance N00-20-00E, 2723.2' to the Northwest corner of Section 6 and S00-20-00W, 2635' to the Southwest corner of Section 6. He does not mention setting or referencing this corner. (SEE REVERSE SIDE) B. Description of corner evidence found. Found and accepted a 1 1/4" O.D. Pipe with 4" diameter Michigan Department of Natur. Resources Aluminum Tablet 0.6' above ground. Pipe is painted orange. Checked Line Call: South, 13.1 chains (864.6'), Stream 4 links (2.60'), courselvest. With a hip chain we measured 907' South to the centerline of a 5' wide stream. Distance North is 2705.66' in painted orange. Checked Line Call: South, 13.1 chains (864.6'), Stream 4 links (2.60'), courselvest. Wit	I, GERALD W. CARLSON	, in a field survey on N	<u>May 21st</u> , 19 <u>99</u> , do	
required in the current manual of survey instructions of the United States Department of the hoterior, Breasu of Land Management or by a decree of a Court of Law and/for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: A-2; Querter corner common to Section 6, 745N-R25W and Section 1, T45N-R25W. A124. William A. Burt's original township boundary survey notes describe the corner monument as a wood post referenced by: 10° Spruce S85W, 31L 12" Maple N36E, 29L 1909-1913: Charles Cummings' notes indicate that he determined the quarter corner of Section 7 from original SLO bearing trees. No description or references given. His notes indicate the quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6. He does not mention setting or referencing this corner. (SEE REVERSE SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (SEE REVERSE SIDE) B. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-2; 1999: No original corner evidence found, Found and accepted a 1 1/4" 0.D. Pipe with 4" diameter Michigan Department of Natur. Resources Aluminum Tablet 0.6" above ground. Pipe is painted orrange. Checked Line Call: South, 13.1 chains (864.6"), Stream 4 links (2.60"), course-West. With a hip chain we measured 907' South to the centerline of a 5' wide stream. Distance North is 2705.66" and South is 2617.80". C. Description of monument for corner and accessories estab				
Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3. 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: A-2; Quarter corner common to Section 6, T45N-R25W and Section 1, T45N-R25W. R244; William A, Burt's original township boundary survey notes describe the corner monument as a wood post referenced by: 10' Spruce S85W, 31L 12' Maple N36E, 29L 1909-1913: Charles Cummings' notes indicate that he determined the quarter corner location by pro-rating his distance between the Northwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing trees. No description or references given. His notes indicate the quarter corner would be located a distance NOr2-OOE, 273-2.2' to the Northwest corner of Section 6 and 500-20-00W, 2835' to the Southwest corner of Section 7 from original GLO bearing trees. No description or references given. His notes indicate the quarter corner of Section 7 from original GLO bearing trees. No description or references given. His notes indicate the quarter corner of Section 7 from original GLO bearing referencing this corner. (SEE REVERSE SIDE) B. Description of corner evidence found. Found and accepted a 1 1/4" O.D. Pipe with 4" diameter Michigan Department of Natur Resources Aluminum Tablet 0.6' above ground. Pipe is painted orange. Checked Line Call: South, 13.1 chains (864.6'l), Stream 4 links (2.60'), course-West. With a hip chain we measured 907' South to the centerline of a 5' wide stream. Distance North is 2705.66' and South is 2617.80'. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-2: 1	required in the current manual	of survey instructions of the U	Inited States Department of the	
Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: A.2: Quarter corner common to Section 6, T45N-R25W and Section 1, T45N-R26W. 1844: William A. Burt's original township boundary survey notes describe the corner monument as a wood post referenced by: 10° Spruce S85W, 31L 12" Maple N36E, 29L 1909-1913: Charles Cummings' notes indicate that he determined the quarter corner location by pro-rating his distance between the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing trees. No description or references given. His notes indicate the quarter corner would be located a distance N00-20-00E, 2723.2' to the Northwest corner of Section 6 and S00-20-00W, 2635' to the Southwest corner of Section 6. He does not mention setting or referencing this corner. (SEE REVERSE SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-2: 1999: No original corner evidence found. Found and accepted a 1 1/4" O.D. Pipe with 4" diameter Michigan Department of Natur. Resources Aluminum Tablet 0.6' above ground. Pipe is painted orange. Checked Line Call: South, 13.1 chains (846.6'), Stream 4 links (2.60'), course-West. With a hip chain we measured 907' South to the centerline of a 5' wide stream. Distance North is 2705.66' and South is 2617.80'. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-2: 1999: Stamped the existing monument with MCR 1999. Monument is 0.6' above ground. Measured found references: 10' W. Pine N76E, 74,70' (DNR NBT-1993) 8' R. Maple S85E, 21.70' (DNR NBT-1993) 5' W. Pine	Interior, Bureau of Land Manager	nent or by a decree of a Court of	Law and/or that the corner points	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: A-2: Quarter corner corner to Section 6, T45N-R25W and Section 1, T45N-R26W. 1844: William A. Burt's original township boundary survey notes describe the corner monument as a wood post referenced by: 10° Spruce S85W, 31L 12" Maple N36E, 29L 1909-1913: Charles Cummings' notes indicate that he determined the quarter corner location by pro-rating his distance between the Northivest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing trees. No description or references given. His notes indicate the quarter corner of Section 7 from original GLO bearing trees. No description or references given. His notes indicate the quarter corner of Section 7 from original GLO bearing trees. No description or references given. His notes indicate the quarter corner of Section 6. He does not mention setting or referencing this corner. SEE REVERSE SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing comer: A-2: 1999: No original corner evidence found. Found and accepted a 1 1/4" O.D. Pipe with 4" diameter Michigan Department of Natura Resources Aluminum Tablet 0.6' above ground. Pipe is painted orange. Checked Line Call: South, 13.1 chains (864.6'), Stream 4 links (2.60'), course-West. With a hip chain we measured 907' South to the centerline of a 5' wide stream. Distance North is 2705.66' and South is 2617.80'. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-2: 1999: Stamped the existing monument with MCR 1999. Monument is 0.6' above ground. Measured found references: 10' W. Pine N76E, 74.70' (DNR NBT-1993) 8" R. Maple S55E, 21.70' (DNR NBT-1993) 5' W. Pine S49E, 13.87' (DNR NBT-1993	mentioned in lines 3, 4 and 5 at Land Surveyors or by a Decre	e of a Court of Law; establish	ed, re-established, monumented,	'
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: A-2: Quarter corner common to Section 6, T45N-R25W and Section 1, T45N-R26W. 1844: William A. Burt's original township boundary survey notes describe the corner monument as a wood post referenced by: 10° Spruce S85W, 31L 12" Maple N36E, 29L 1909-1913: Charles Cummings' notes indicate that he determined the quarter corner location by pro-rating his distance between the Northwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing trees. No description or references given. His notes indicate the quarter corner would be located a distance N00-20-00E, 2723.2' to the Northwest corner of Section 6 and solo-20-00W, 2635' to the Southwest corner of Section 6. He does not mention setting or referencing this corner. (SEE REVERSE SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-2: 1999: No original corner evidence found. Found and accepted a 1 1/4" O.D. Pipe with 4" diameter Michigan Department of Natura Resources Aluminum Tablet 0.6" above ground. Pipe is painted orange. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-2: 1999: Stamped the existing monument with MCR 1999. Monument is 0.6" above ground. Measured found references: A-2: 1999: Stamped the existing monument with MCR 1999. Monument is 0.6" above ground. Measured found references: B. R. Maple N72E, 93.02' Green Steel Sign Post w/ Yellow Survey Marker Sign North, 4.12' Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.				
A. Description of original monument and accessories and/or subsequent restoration: A-2: Quarter corner common to Section 6, T45N-R25W and Section 1, T45N-R26W, and Section 1, T45N-R26W, and Section 6, T45N-R25W and Section 1, T45N-R26W, and Section 6, T45N-R25W, and Section 6, T45N-R26W, and Section 7,	NOTE: Not more than 2 cor	rners, all in the same town and	d range, may be recorded	
A. Description of original monument and accessories and/or subsequent restoration: A-2: Querter corner common to Section 6, T45N-R25W and Section 1, T45N-R26W. 1844: William A. Burt's original township boundary survey notes describe the corner monument as a wood post referenced by: 10° Spruce S85W, 31L 12" Maple N36E, 29L 1909-1913: Charles Cummings' notes indicate that he determined the quarter corner location by pro-rating his distance between the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing trees. No description or references given. His notes indicate the quarter corner would be located a distance N00-20-00E, 2723.2' to the Northwest corner of Section 6 and S00-20-00W, 2635' to the Southwest corner of Section 6. He does not mention setting or referencing this corner. (SEE REVERSE SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-2: 1999: No original corner evidence found. Found and accepted a 1 1/4" O.D. Pipe with 4" diameter Michigan Department of Natur. Resources Aluminum Tablet 0.6" above ground. Pipe is painted orange. Checked Line Call: South, 13.1 chains (864.6"), Stream 4 links (2.60"), course-West. With a hip chain we measured 907' South to the center/line of a 5" wide stream. Distance North is 2705.66" and South is 2617.80". C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-2: 1999: Stamped the existing monument with MCR 1999. Monument is 0.6" above ground. Measured found references: 10° W. Pine N76E, 74.70" (DNR NBT-1993) 8" R. Maple S85E, 21.70" (DNR NBT-1993) 5" W. Pine S49E, 13.87" (DNR NBT-1993) 7" W. Pine S45W, 1.50" (DNR NBT-1993) 5" W. Pine S49E, 13.87" (DNR NBT-1993) 7" W. Pine S45W, 1.50" (DNR NBT-1993)				11
A-2: Quarter corner common to Section 6, T45N-R25W and Section 1, T45N-R26W. 1844: William A. Burt's original township boundary survey notes describe the corner monument as a wood post referenced by: 10° Spruce S85W, 31L 12" Maple N36E, 29L 1909-1913: Charles Cummings' notes indicate that he determined the quarter corner location by pro-rating his distance between the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing trees. No description or references given. His notes indicate the quarter corner would be located a distance NO0-20-00E, 2723.2' to the Northwest corner of Section 6 and S00-20-00W, 2635' to the Southwest corner of Section 6. He does not mention setting or referencing this corner. (SEE REVERSE SIDE) B. Description of corner evidence found. Found and accepted a 1 1/4" O.D. Pipe with 4" diameter Michigan Department of Natura Resources Aluminum Tablet 0.6' above ground. Pipe is painted orange. Checked Line Call: South, 13.1 chains (864.6'), Stream 4 links (2.60'), course-West. With a hip chain we measured 907' South to the centerline of a 5' wide stream. Distance North is 2705.66' and South is 2617.80'. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-2: 1999: Stamped the existing monument with MCR 1999. Monument is 0.6' above ground. Measured found references: 10° W. Pine N76E, 74.70' (DNR NBT-1993) 8" R. Maple S85E, 21.70' (DNR NBT-1993) 5° W. Pine S49E, 13.87' (DNR NBT-1993) 7" W. Pine S45W, 1.50' (DNR NBT-1993) Established new reference: 3" Maple N72E, 93.02' Green Steel Sign Post w/ Yellow Survey Marker Sign North, 4.12' Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixe				
1844: William A. Burt's original township boundary survey notes describe the corner mountains as a wood post referenced by: 10" Spruce S85W, 31L 12" Maple N36E, 29L 1909-1913: Charles Cummings' notes indicate that he determined the quarter corner location by pro-rating his distance between the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing trees. No description or references given. His notes indicate the quarter corner would be located a distance NOO-20-00E, 2723.2' to the Northwest corner of Section 6 and SOO-20-00W, 2635' to the Southwest corner of Section 6. He does not mention setting or referencing this corner. (SEE REVERSE SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-2: 1999: No original corner evidence found. Found and accepted a 1 1/4" 0.D. Pipe with 4" diameter Michigan Department of Natura Resources Aluminum Tablet 0.6' above ground. Pipe is painted orange. Checked Line Call: South, 13.1 chains (864.6'), Stream 4 links (2.60'), course-West. With a hip chain we measured 907' South to the centerline of a 5' wide stream. Distance North is 2705.66' and South is 2617.80'. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-2: 1999: Stamped the existing monument with MCR 1999. Monument is 0.6' above ground. Measured found references: 10' W. Pine N76E, 74.70' (DNR NBT-1993) 8" R. Maple S85E, 21.70' (DNR NBT-1993) 5" W. Pine S49E, 13.87' (DNR NBT-1993) 7" W. Pine S45W, 1.50' (DNR NBT-1993) 5" W. Pine S49E, 13.87' (DNR NBT-1993) 7" W. Pine S45W, 1.50' (DNR NBT-1993) 6" W. Pine S49E, 13.87' (DNR NBT-1993) 7" W. Pine S45W, 1.50' (DNR NBT-1993)				13
1909-1913: Charles Cummings' notes indicate that he determined the quarter corner location by pro-rating his distance between the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing trees. No description or references given. His notes indicate the quarter corner would be located a distance NOO-20-00E, 2723.2' to the Northwest corner of Section 6 and SOO-20-00W, 2635' to the Southwest corner of Section 6. He does not mention setting or referencing this corner. (SEE REVERSE SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-2: 1999: No original corner evidence found. Found and accepted a 1 1/4" O.D. Pipe with 4" diameter Michigan Department of Natura Resources Aluminum Tablet 0.6' above ground. Pipe is painted orange. Checked Line Call: South, 13.1 chains (864.6'), Stream 4 links (2.60'), course-West. With a hip chain we measured 907' South to the centerline of a 5' wide stream. Distance North is 2705.66' and South is 2617.80'. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-2: 1999: Stamped the existing monument with MCR 1999. Monument is 0.6' above ground. Measured found references: 10' W. Pine N76E, 74.70' (DNR NBT-1993) 8" R. Maple S85E, 21.70' (DNR NBT-1993) 5' W. Pine S49E, 13.87' (DNR NBT-1993) 7" W. Pine S45W, 1.50' (DNR NBT-1993) Established new reference: 8" Maple N72E, 93.02' Green Steel Sign Post w/ Yellow Survey Marker Sign North, 4.12' Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.	1844: William A. Burt's origin	nal township boundary survey	notes describe the corner	RATIFIED BY PEER GROUP
1909-1913: Charles Cummings' notes indicate that he determined the quarter corner location by pro-rating his distance between the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. No description or references given. His notes indicate the quarter corner would be located a distance NOO-20-00E, 2723.2' to the Northwest corner of Section 6 and SOO-20-00W, 2635' to the Southwest corner of Section 6. He does not mention setting or referencing this corner. (SEE REVERSE SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-2: 1999: No original corner evidence found. Found and accepted a 1 1/4" O.D. Pipe with 4" diameter Michigan Department of Natura Resources Aluminum Tablet 0.6' above ground. Pipe is painted orange. Checked Line Call: South, 13.1 chains (864.6'), Stream 4 links (2.60'), course-West. With a hip chain we measured 907' South to the centerline of a 5' wide stream. Distance North is 2705.66' and South is 2617.80'. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-2: 1999: Stamped the existing monument with MCR 1999. Monument is 0.6' above ground. Measured found references: 10' W. Pine N76E, 74.70' (DNR NBT-1993) 8" R. Maple S85E, 21.70' (DNR NBT-1993) 5" W. Pine S49E, 13.87' (DNR NBT-1993) 7" W. Pine S45W, 1.50' (DNR NBT-1993) 5" W. Pine S49E, 93.02' Green Steel Sign Post w/ Yellow Survey Marker Sign North, 4.12' Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.	•		N36F 29I	
1909-1913: Charles Cummings' notes indicate that he determined the quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 with the GLO distance. He mentions setting the Northwest corner of Section 6 and the West quarter corner of Section 7 from original GLO bearing trees. No description or references given. His notes indicate the quarter corner would be located a distance N00-20-00E, 2723.2' to the Northwest corner of Section 6 and S00-20-00W, 2635' to the Southwest corner of Section 6. He does not mention setting or referencing this corner. (SEE REVERSE SIDE) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-2: 1999: No original corner evidence found. Found and accepted a 1 1/4" O.D. Pipe with 4" diameter Michigan Department of Natura Resources Aluminum Tablet 0.6' above ground. Pipe is painted orange. Checked Line Call: South, 13.1 chains (864.6'), Stream 4 links (2.60'), course-West. With a hip chain we measured 907' South to the centerline of a 5' wide stream. Distance North is 2705.66' and South is 2617.80'. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-2: 1999: Stamped the existing monument with MCR 1999. Monument is 0.6' above ground. Measured found references: 10' W. Pine N76E, 74.70' (DNR NBT-1993) 8" R. Maple S85E, 21.70' (DNR NBT-1993) 5" W. Pine S49E, 13.87' (DNR NBT-1993) 7" W. Pine S45W, 1.50' (DNR NBT-1993) Established new reference: 3" Maple N72E, 93.02' Green Steel Sign Post w/ Yellow Survey Marker Sign North, 4.12' Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.	TO Spruce Soow,	OIE 12 Mahie	11000, 200	10/25/99
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-2: 1999: No original corner evidence found. Found and accepted a 1 1/4" O.D. Pipe with 4" diameter Michigan Department of Natura Resources Aluminum Tablet 0.6' above ground. Pipe is painted orange. Checked Line Call: South, 13.1 chains (864.6'), Stream 4 links (2.60'), course-West. With a hip chain we measured 907' South to the centerline of a 5' wide stream. Distance North is 2705.66' and South is 2617.80'. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-2: 1999: Stamped the existing monument with MCR 1999. Monument is 0.6' above ground. Measured found references: 10" W. Pine N76E, 74.70' (DNR NBT-1993) 8" R. Maple S85E, 21.70' (DNR NBT-1993) 5" W. Pine S49E, 13.87' (DNR NBT-1993) 7" W. Pine S45W, 1.50' (DNR NBT-1993) Established new reference: 8" Maple N72E, 93.02' Green Steel Sign Post w/ Yellow Survey Marker Sign North, 4.12' Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.	location by pro-rating his distance. He mentions setting trees. No description or refere Northwest corner of Section (ance between the Northwest of the Northwest corner of Secences given. His notes indicate	corner of Section 6 and the W ction 6 and the West quarter c a the quarter corner would be	est quarter corner of Section 7 with the GLO orner of Section 7 from original GLO bearing located a distance N00-20-00E, 2723.2' to the
A-2: 1999: No original corner evidence found. Found and accepted a 1 1/4" O.D. Pipe with 4" diameter Michigan Department of Natura Resources Aluminum Tablet 0.6' above ground. Pipe is painted orange. Checked Line Call: South, 13.1 chains (864.6'), Stream 4 links (2.60'), course-West. With a hip chain we measured 907' South to the centerline of a 5' wide stream. Distance North is 2705.66' and South is 2617.80'. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-2: 1999: Stamped the existing monument with MCR 1999. Monument is 0.6' above ground. Measured found references: 10" W. Pine N76E, 74.70' (DNR NBT-1993) 8" R. Maple S85E, 21.70' (DNR NBT-1993) 5" W. Pine S49E, 13.87' (DNR NBT-1993) 7" W. Pine S45W, 1.50' (DNR NBT-1993) Established new reference: 8" Maple N72E, 93.02' Green Steel Sign Post w/ Yellow Survey Marker Sign North, 4.12' Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.	(SEE REVERSE SIDE)			
A-2: 1999: Stamped the existing monument with MCR 1999. Monument is 0.6' above ground. Measured found references: 10" W. Pine N76E, 74.70' (DNR NBT-1993) 8" R. Maple S85E, 21.70' (DNR NBT-1993) 5" W. Pine S49E, 13.87' (DNR NBT-1993) 7" W. Pine S45W, 1.50' (DNR NBT-1993) Established new reference: 8" Maple N72E, 93.02' Green Steel Sign Post w/ Yellow Survey Marker Sign North, 4.12' Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.	A-2: 1999: No original corner Resources Aluminum Tablet C Checked Line Call: South, 13	r evidence found. Found and a 0.6' above ground. Pipe is pair .1 chains (864.6'), Stream 4 I	iccepted a 1 1/4" O.D. Pipe w inted orange. inks (2.60'), course-West . W	ith 4" diameter Michigan Department of Natural
8" Maple N72E, 93.02' Green Steel Sign Post w/ Yellow Survey Marker Sign North, 4.12' Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.	A-2: 1999: Stamped the exis 10" W. Pine N76E,	ting monument with MCR 199 74.70' (DNR NBT-1993)	99. Monument is 0.6' above g 8" R. Maple S85E,	round. Measured found references : 21.70' (DNR NBT-1993)
Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.		93.02'		
	Green Steel Sign Post w/ Yeli	low Survey Marker Sign No	orth, 4.12'	
			lazes, d.h. measuring nails, an	d stamped B.T. Tags affixed. GERALD W.

24589 Surveyor's Michigan License No.____

Date 12-8-69

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1963 REVISED OCT., 1995

SURVEYOR No.

A-2: PART A CONTINUED:

1990: An Easement Description Map by Sundberg, Carlson and Associates, Inc., indicates the quarter corner. No description or accessories given.

1993: An LCRC recorded by Paul R. Bressette, P.S. #37270, in L.5 RC, Pg.383 indicates that he set a DNR monument by single proportionate measurement between the Northwest and Southwest corners of Section 6. Referenced by:
9" W. Pine N81E, 74.35' 8" R. Maple S79E, 21.70'

8" 5"

W. Pine

\$44E,

13.70'

W. Pine

S55W,

1.30'

Jan M 200

SECTION