

4, 12 2 2 1999

MARQUE	HE	CGUNTY	•
RECEIVE	CHIG. D FOI	AN B-ROOM	P

1978 DEC 16 PH 3: 20

LAND CORNER RECORDATION CERTIFICATE SECTION Filing Requirement of Act 74, Mich. P.A. 1970 For corners in REGISTER OF DEEDS of MARQUETTE Located In: Corner Code # 1. Public Land Survey T 45N R 25W A-13 T 44N R 25W A-1 T<u>44N</u>R<u>26W</u> M-1 T 45N R 26W M-13 2. Property Controlling in Section LIBER \mathbf{R} 2 PAGE 71 Miscellaneous Property in Sec. Register of Deeds Stamp & File Num __ , Recorded Plat __ 4. Lot No. 5. Private Claims 2 , in a field survey on GERALD W. CARLSON MAY 20TH 3 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points 4 mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, 5 Bureau of Land Management or by a decree of a Court of Law and/or that the corner points 6 mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded 29 on this certificate. 11 A. Description of original monument and accessories and/or subsequent restoration: A-13: Corner common to Section 31, T45N-R25W; Section 6, T44N-R25W; Section 1, T44N-R26W; and Section 36, T45N-R26W. 1844: William A. Burt's original survey notes describe the corner monument as a wood post referenced by: 12" Y. Birch N25W, 20 L 36" W. Pine S15E, 49 L 1977: An LCRC recorded by William R. Donnan P.S. #17618 in L. 1, RC Pg. 201 indicates no original corner evidence found. He found 3/4" Iron Rod. Referenced by: 15" W. Pine 6.65 25.04 N54E. 8" Balsam S17E, 15" W. Pine S82W. 17.201 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: A-13: 1998: No original corner evidence found. Found and accepted a 3/4" - 1" Tapered Iron Rod, 1.7' high. Found unrecorded referen tree with nail and washer #20711as described in Part C below. Bearings and distances to found references check well with those recorded in L. 1, RC Pg. 201, except the 15" White Pine (S82W, 17.20') is actually a Red Pine. Distance East is 2553.87. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: A-13: 1998: Replaced found Iron with a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette Count Survey Monument stamped to identify the corner. Measured found references: 6.51' (to set d.h. nail)(Donnan NBT 8" Balsam (dead) S13E, 25.12' (Donnan NBT) 19" W. Pine N55E. 16" W. Pine 27.19' (to nail/washer RLS #20711) Robey NBT) S65E. 18" R. Pine 17.22' (to set d.h. nail) (Donnan NBT) S82W. Established references: 9" Maple S25W, 62.291 Green Steel Sign Post w/ Yellow Survey Marker Sign Due South, 1.65 Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed. Bk. 12, pp. 64-65.

RATIFIED BY PEER GROUP any & Bussone GERALD W CARLSON SURVEYOR No.

Surveyor's Michigan License No.