

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 27W


Marquette COUNTY

DESCRIPTION OF CORNER 1/4 Cor. bet Secs. 28-33

CORNER MONUMENT 2" Iron Pipe

DATE MONUMENT PLACED AND WITNESSED 8/15/66

WITNESSES TO CORNER..... 20" W. Pine (1/2 S NBT) S33°E 41.8'



16" Tamarack (1/2 S NBT) N76°W 39.0

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed as set by unknown surveyor. Found pipe in place with a 20" W. Spruce, N70°W 40 lks., marked as a witness.

Corner lies on east side of a small brook and in line with a single wire fence to west.

Found steel drill rod 68 lks. to east of this corner. Appears to have been set recently.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 1/10/67
REGISTERED LAND SURVEYOR