


MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 45 N.R. 27 W


Marquette COUNTY

DESCRIPTION OF CORNER E 1/16 between Secs. 18-19

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6/30/65

WITNESSES TO CORNER..... 14" Jackpine (1/16 BT), S 10° W, 69.5 lks.



10" Jackpine (BT), N 46° E, 90.5 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies in North edge of sharptail burn area in a fire plow furrow.

Corner placed between Section Corner to East and 1/4 Corner to West.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 4/29/1966