

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 27W


Marquette COUNTY

DESCRIPTION OF CORNER $\frac{1}{4}$ cor. bet. Secs. 16-21

CORNER MONUMENT 1" Pipe with 4" Alum. Cap.

DATE MONUMENT PLACED AND WITNESSED 5/27/66

WITNESSES TO CORNER..... 10" Jack Pine ($\frac{1}{4}$ S NBT) N61° W 28.9'



9" Red Oak ($\frac{1}{4}$ S NBT) East 31.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line bet. two Sec. Cors. Found no evidence of original corner.

Corner lies on an old logging grade bearing N. - S.

SURVEYOR'S SEAL

Billy D. Buckler.
SIGNED Billy D. Buckler DATE 12/30/66
REGISTERED LAND SURVEYOR