

✓

**MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION**

LAND CORNER RECORD

T. 45N N.R. 27W


Marquette COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 14-15-22-23

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9/1/66

WITNESSES TO CORNER..... 8" Red Pine (S23 NBT) S68°E 132.5'



5" Jack Pine (S22 NBT) S12°W 69.5'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at an old wood post, set by unknown surveyor. Found a tamarack stump bottom bearing N47°E 31 links. No evidence of marks or blazes.

Corner lies in a small open marsh.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler* DATE 1/11/67
REGISTERED LAND SURVEYOR