

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 27W


Marquette COUNTY

DESCRIPTION OF CORNER 1/4 Corner bet. Secs. 25-36

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 9/14/66

WITNESSES TO CORNER..... 9" Cedar (1/2 S NBT) S80°W 4.4'



8" Cedar (1/2 S NBT) N42°E 5.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at location of several old blazes. Found line of blazes to east for 1/2 mile and a good corner 39.77 chs. from here.

Corner lies 1/2 chain north of lake.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 1/11/67
REGISTERED LAND SURVEYOR