

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45N N.R. 27W


Marquette COUNTY

DESCRIPTION OF CORNER 1/4 Cor. bet. Secs. 4-9

CORNER MONUMENT 2" Iron Pipe with 3" Brass cap.

DATE MONUMENT PLACED AND WITNESSED 8/25/66

WITNESSES TO CORNER..... 18" Red Pine N56°W 31 lks.



12" jack pine S30°E 59 1/2 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-witnessed. Found iron pipe as placed by unknown surveyor, with probable B.T., a w. pine bearing N71°W 19 links. Tree down and in poor condition.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 1/11/67
REGISTERED LAND SURVEYOR