

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. ~~44-45~~ NR. 27 W. . .

Dickinson and Marquette . . . COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 3 and 34. . . . .

DESCRIPTION OF CORNER MONUMENT . . . . .

WITNESSES TO CORNER . . . 8" Red Pine S 87 E . . . 93 $\frac{1}{2}$  Links . . . . .  
Marked "1/4 S NBT"  
6" Soft Maple N 13 W . . . 54 Links . . . . .  
Marked "1/4 S NBT"  
. . . . .  
. . . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two Jack Pine B.T.'s bearing N 62 $\frac{1}{2}$  E, 31 Links, face and notch plain, stp. burnt. Also N 51 $\frac{1}{2}$  W, 12 Links, stp. rotted, found trace of blaze and overgrowth.

Corner found by Forestry Division Survey Crew.

Set corner with F. Bray, Norway.

Corner was placed and witnessed on 22 May 1958.

SURVEYORS SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 4-15-59  
REGISTERED LAND SURVEYOR