MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T45846 NR _28 W_

		Ma_r_q_u_e_t_t_e	COUNTY
DESCRIPTION O	F CORNER Section	corner common to sections 5	6.31.32
DESCRIPTION OF	CORNER MONUME	NT 1" Iron Pipe with 4" Bra	ss_Cap.
WITNESSES TO	CORNER 10" Oak	(S_5_NBT)	46_1/2_Links
	_ 9"_JP	ine (S_32 NBT) N 59° E _ 8	8 <u>8 Links</u>
	_ 7	ine_ (s_6_NBT) _ \$ 30° W	91 Links
	_ 7"_ Oak_	(S_31_NBT) N_38° W	99 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from 3 original B.T.'s. One in fair condition other two pine stumps in proper positions.

Corner was placed and witnessed July 14, 1959.

SURVEYORS SEAL

REGISTERED LAND SURVEYOR

DATE 4/28/60

Billy D. Buckler