

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 45.. NR 28 & 29 W

M a r g u e t t e COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 1, 6, 7, 12

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap.

WITNESSES TO CORNER 10" Oak (S 7 NBT) S 22° E 67 Links

8" Oak (S 6 NBT) N 75° E 55 1/2 Links

10" Oak (S 1 NBT) N 38° W 62 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from three pine stumps in proper positions. No marks visible.

Corner was placed and witnessed January 14, 1959.

SURVEYORS SEAL

SIGNED *Billy D. Buckler* DATE 4-28-60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler