LAND CORNER RECORDATION CERTIFICATE

Fo	r corners in	Filing Requirement of Act 74, Mich. P.A. 1970														
T Marquette		Located In:		in:	Corner Code ≠#											
-	(County)	Localed III.														
1.	Public Land Survey		T 45N	R 28W	C4											
			T	R												
			Τ	R												
			T ,	R												
2.	Property Controlling	S	T	R		1										
	in Section	S	Ŧ	R												
3.	Miscellaneous	S.	T	A		l Re	giste	r of	Dee	de S	tiam		ita	Num	her	
	Property in Sec.	S	T	A			_									
4.	Lot No ,	Recorded	Plat				_ ,						u			
5.	Private Claims	-					- 6	Ť	Ť	Ť	ìή	Ť	Ü	İΤ	Ť	רֿדׂ
							1	— å-	+-	6 —	╂╌ᢤ╌	+-	ف	┝╬╌	+-	::-
							<u> </u>	\dashv	T	1	1	+	┥╌	\vdash	+	${m H}$
. 1	with Carbatt	in a fia	lel aa	. Warch 16	. 19	90][- ₁ -	7	!-	†	†	10— 1	1- 	†-	12
					of 1970, the corner points me		°t	十	+-	†	 	+-	t	\vdash	+	H
					rules therefore as require		*	-1/8-	+-	? —	18-	+-1	5-	1/4-	+	j 3—
					ment of the Interior, Bureau		- 7∤	+	+	₩	⊢∔	+	١.,	-	-1-	Н
					points mentioned in lines 3,		•	_1 J	┶	20	_21-	-	2-	—23-	┸	Į.
					Land Surveyors or by a Dec onumented, recovered, to		•	_	┸	$oldsymbol{\perp}$	ш	⅃ ــ	Ш	1		Ш

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C4 Original monument and accessories not found.

expressed below:

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C4 Restored midway and on line.

C Description of monument for corner and accessories established to perpetuate locating the position of the corner.

C4
Set 1" ID x 32" iron pipe
v/plastic cap.
10" cedar S83W 1.8' squared
6" cedar S20W 2.8' 1/4s, MBT
8" cedar W04W 12.3' 1/4s, MBT
6" cedar M47E 19.0' 1/4s, MBT

Signed by Jew Jackett
Surveyor's Michigan License No. 19006

MESSAL MANDE TO

August 27, 1990

REVISED MAY 14, 1975

REVISED JAN , 1983