

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 .. NR. 29 .. W

Marquette COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 28 and 33

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 16" Red Oak (1/4" NBT) East 03 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two Section Corners. No evidence of original corner. Corner lies on north edge of hill.

Corner was placed and witnessed May 20, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 8/11/60 ..
REGISTERED LAND SURVEYOR
Billy D. Buckler