

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. ~~45~~46 NR. 29. W.

Marquette COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 1, 2, 35, 36

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 9" Red Oak (S 2 NBT) S 72° W 51 1/2 Links

10" Red Pine (S 36 NBT) N 25° E 17 Links

10" Red Pine (S 1 NBT) S 62° E 18 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced at old wood post believed set by Ford Motor Company Surveyors. Position checks with other corners in area. No evidence of original corner.

Corner was placed and witnessed September 28, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 4/27/60
REGISTERED LAND SURVEYOR
Billy D. Buckler