MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T 45 NR 29 W

				Ma:	r q u e t	<u>t</u> •	COUNTY
DESCRIPTION	OF	CORNER	1/4 corner	petween [Sections 3	and 10_	
DESCRIPTION	OF	CORNER	MONUMENT	l" Pipe t	gith 4" Br	ass Cap	
WITNESSES	то	CORNER	20" W. Pine		nbt)	49° W	85_Linka
			26" Red Pine		MBT) s	39°_E	82 Links
				-		. 	
				. -			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from W. Pine Stump (probable B.T.) bearing N 33° E 12 Links. Position fits well with Section Corners east and west.

Corner was placed and witnessed September 29, 1959 with Frank J. Bray.

SURVEYORS SEAL

REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 4/12/60 _