

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 45. NR. 29. W

Marquette COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 11 and 14

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 7" Red Oak (1/4s NBT) S 54° W 42 1/2 Links

6" Red Oak (1/4s NBT) N 32° W 04 Links

5" Red Oak (1/4s NBT) N 60° E 05 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established midway and on line between two Section Corners. No evidence of original corner.

Corner was placed and witnessed September 29, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 4/11/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler