MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_45_NR_29_W

	_ M_a_r_q u e t t e COUNT
DESCRIPTION OF CORNER	Section corner common to Sections 26,27,34,35
DESCRIPTION OF CORNER	MONUMENT_1" Pipe with 4" Brass Cap
WITNESSES TO CORNER	24" Red Pine _ (S_34 NBT) _ S_80° W _ 84 Links
	7" Red Oak (S 35 NBT) S 10° E 103 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established by double proportionate measure from 1/4 corner, 1/2 mile north; Section corner, 1 mile east; Section corner 1 mile south; and Section corner 2 miles west. No evidence of original corner.

Corner was placed and witnessed August 13, 1959 with R. Hinds, Norway.

SURVEYORS SEAL

REGISTERED LAND SURVEYOR

Billy D. Buckler

ATE _4/22/60_