

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 .. NR. 29 .. W

.. M a r q u e t t e .. COUNTY

DESCRIPTION OF CORNER .. 1/4 Corner between Sections 26 and 35 ..

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap ..

WITNESSES TO CORNER 12" W. Pine .. (1/4s NBT) .. N 48° E .. 41 Links ..

15" Yellow Pine (1/4s NBT) .. S 48° W .. 53 Links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced midway and on line between Section corners.

No evidence of original B.T.'s.

Corner was placed and witnessed July 13, 1959.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 4/28/60