## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T 45 NR 29 W

		MarquetteCOUNTY
DESCRIPTION	OF CORNER	Section_corner_common_to_Sections_2, 3, 10, 11.
DESCRIPTION	OF CORNER	MONUMENT_1" Iron Pipe with 4" Brass Cap.
WITNESSES	TO CORNER	13" J. Pine (S_10 NBT) S_5° W 89 Links
		Y_Pine (S_3_NBT) _ N 32° W _ 1,12 Chains .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from original B.T. to NW (Iron marks visible on stump bottom in proper position to S E)

Corner was placed and witnessed July 16, 1959.

SURVEYORS SEAL

SIGNED Silly & Suckler

REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 4/28/60