## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T\_45\_ NR\_\_29\_\_W

_ <u>H_a_r_q_u_e_t_t_eCOUNT</u>
DESCRIPTION OF CORNER 1/4 Corner common to Sections 22 and 27.
DESCRIPTION OF CORNER MONUMENTI Iron Pipe with 4" Brass Cap
WITNESSES TO CORNER _8" Oak(1/4s_NBT)S_560 W 52 1/2 Links
8"_0ak (1/4s_NBT)N_14°_E _ 87_Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced midway and on line between Section Corners.

No original evidence found.

Corner was placed and witnessed July 15, 1959.

SURVEYORS SEAL

REGISTERED LAND SURVEYOR

DATE 4/28/60

Billy D. Buckler