

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 . . . NR . . . 29 . . . W

. . . M a r q u e t t e COUNTY

DESCRIPTION OF CORNER Section corner common to Section 20, 21, 28, 29

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

WITNESSES TO CORNER 7" J. Pine (S 29 NBT) . . . S 56° W . . . 25 Links

8" J. Pine (S 20 NBT) . . . N 37° W . . . 57 Links

4" Red Pine (S 21 NBT) . . . N 76° E . . . 48 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from White Pine stump bottom, stream and Section corners to East and South fit.

Corner was placed and witnessed July 27, 1959.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 4/28/60
REGISTERED LAND SURVEYOR
Billy D. Buckler