

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 45 N.R. 29 W


Marquette COUNTY

DESCRIPTION OF CORNER 1/4 corner for Sections 33 and 34

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 9/29/60

WITNESSES TO CORNER.... 6" Cedar (1/4^s NBT) S 82° E 32 Links



7" Cedar (1/4^s NBT) 38 1/2 Links N 84° W

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from 20" W. Pine, N 62 1/2° W, 165 links in poor condition with face with axe marks and possible iron marks. Cedar stump in proper bearing and distance but no evidence of marks.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler

REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 2/23/61