

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 45. NR. 30. E

----- Marquette ----- COUNTY

DESCRIPTION OF CORNER Meander corner on W. side of Squaw Lake between Sections  
9 & 16

DESCRIPTION OF CORNER MONUMENT 3/4" Pipe in Roofs of tree -----

WITNESSES TO CORNER -- 12" Hemlock - N 76 E - 12 Links -----

-- 9" Hemlock - West - 34 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

This corner was pointed out to me by D. Zettle, Regional Forester, of  
Marquette. Original corner (squared Hemlock) still in place, excellent condition.

Corner was located and witnessed October 7, 1952.

SURVEYORS SEAL

SIGNED

*John C. LaRue*  
REGISTERED LAND SURVEYOR

DATE

*3/25/53*