STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

	Marquette	COUNTY
•	T45N	R 30W
DESCRIPTION OF CORNER M.C. on North side of Witch Lake	between Sec.	23 & 24
CORNER MONUMENT 1" I.D. x 36" iron pipe with 4"	aluminum cap	
DATE MONUMENT PLACED AND WITNESSED April 9, 1969		
WITNESSES TO CORNER Red Maple 9 N41°W 39 1ks.	"MC NBT"	
Cedar 11 S482 E 702 1ks.	NNC NBIn	
AND CIRCLE CORNER REGISTERED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Monument placed at an old 1" O.D. x 3° long iron pipe which was set prior to 1943 by an unknown surveyor, from the stumps of two original W. Pine bearing trees. Both stumps are still in position and agree with originals in species, absolute and relative size, and bearing and distance from corner. Both are badly deteriorated, but one has axe marks which may be part of original lower blaze. This corner is reported in a survey by the Marquette County Road Commission on April 30, 1943.

The present variation at this corner appears to be about 6000 East. Variation at time of original survey was 0 55 East.

SURVEYOR'S SEAL

SIGN

NED Urthur O. C

DATE 10/20/69

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing