SURVEY & REMONUMENTATION

MAR 1 3 1998

MARQUELIE COUNTY
HICHIGAN
RECEIVED FOR RECORD

\sim	-	\neg	10	
	-		11 1	II VI
v	-,	~ 1		

Surveyor's Michigan License No. 24589

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1997 DEC 30 PH 1: 45

For corners in MARQUETTE (County)	Located In:	Corner Code #	FIZ RF	Ticis A. Monley GISTER OF DEEDS ON
1. Public Land Survey	T <u>46N</u> R <u>25W</u> T <u>46N</u> R <u>24W</u> TR TR	M-10 A-10	(116.	a
2. Property Controlling S_ in Section S_ 3. Miscellaneous S_	TR		δ.	- ~
Property in Sec. S_	TR		LIBER 2 PAGE	58 Stamp & File Number
4. Lot No, Recorde 5. Private Claims			Negistal Oi Death	Statisp & File Nutriber
I, <u>GERALD W. CARLSON</u> hereby state that under requiremen			1 2 6 - 5 3 3 8 8	4 -3 2 -1
mentioned in lines 1 and 2 above virequired in the current manual of survi	vere in conformance with re ey instructions of the United S	gulations and rules therefore as States Department of the Interior,	"	16 -15 -14 -13
Bureau of Land Management or by mentioned in lines 3, 4 and 5 above Land Surveyors or by a Decree of recovered, found as expressed below:	were in conformance with th a Court of Law; establishe	e rules of the Michigan Board of		
NOTE: Not more than 2 corners on this certificate.	, all in the same town and	range, may be recorded	-	2725
A. Description of original monum M-10: Quarter Corner common to			12 31 - 32 - 32	33 34 35 36
F24W. 1844: William A. Burt's original supost referenced by: 10" Sugar S37W, 20			P.A. 345 OF	(1.2
10" Sugar S37W, 20 No further corner information avai		N36E, 23 L	DATE	12/15/97
B. Description of corner evidence M-10: 1997: No original corner evidence N.E. Corner of Section 36 to the N.E. Corner of Section 36 feet short from decided at the December 15, 199 South of the East 1/4 Corner of Section 1 were proportioned to the East-West position of the N.E. Corner of Section 36 to the N.E. Corner of Section 36 to the N.The distances West to the N.W. a GLO distances. Distance North	idence found. Survey of N.E. Corner of Section 1. It is, location posters and GLC the GLO measurement from 7 Peer Group meeting to prection 1 and the N.E. Corner N.E. Corner of Section 3 mer of Section 13 was Plaint line as the N.E. Corner I.E. Corner of Section 1. Ind S.W. Corners of Section 1.	ontrol was established along to evidence of existing corner of Line Calls were tied in along on the N.E. Corner of Section roportion the East 1/4 Corner er of Section 1. The remaining 6. Each 1/2 mile distance Waced 231' West (GLO - 3.5 cheof Section 13 was placed 29. The remaining stream calls fit	the East Township Lines was found along the the entire 5 mile rout 36 to the N.E. Corner of Section 1 between a 2632.72' by using the centerline 10' West of this calculation at 26 Section 24 also for was found to the extremely well to the error Section 24 also for was found to the section 24 also found to the	is 5 mile section of Ran e. This 5 mile section of r of Section 1. It was the stream call 116' of the East 1/4 Corner of this proportion. The of the stream call East ulated straight line from proportioned corners.
11" Maple S08W, 25. 11" Maple S46W, 30.	uminum pipe capped with onument is 0.1' above gre	a 3 1/4" diameter aluminum to bund on North slope of hill, ne	tablet Marquette Cour ear the Easterly side.	nty Survey Monument Monument is located in
Green Steel Sign Post w/ Yellow S	urvey Marker Sign No	rth, 2.0'	É	THE OF SILES
Note: Bearing trees have painted for d.h. measuring nails, and stamped Bk. 13, Pg. 75-81		z es,	*	GERALD W. CARLSON SURVEYOR No. 24589
Signed by Gurlela	Calson	Date 12-	24-97	The state of the s