## SURVEY & REMONUMENTATION

APR 28 1995

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

1994 DEC 29 PM 1:56

	COMMISS	Siling Requi	rement of Act 74, Mich.	D A 1070	•	_	··· • • •
For corr	ners in	riing nequi	rement of Act 74, with.	F.A. 1970	10	1	1000
	quette	l cented to	Corner Code with	1	0.22	nicen 4.	Monlay &
	(County)	Located In:	Corner Code =##		RE	-disten or	Drens // 🤻
				RATIFIED	BY PEER	GROUP	
1. Pub	lic Land Survey	T 46N R 25W	~~ <u> </u>	P.A. 345	OF 1990		
		T 46N R 24W	(A-12) V	Los	rg ) 6.	Bussin	
		T R		DATE	Sept 26	199U	,
		T R					•
2. Prop	perty Controlling	S T R	<u> </u>				<b>.</b>
in S	ection	S T R	<del></del>			LIBER	1 PAGE 23
3. Misc	cellaneous	S T R	-	Regis	ster of Deeds	Stamp & F	ile Number
Prop	perty in Sec.						
4. Lot	No,	Recorded Plat			A B C C	) E F G	HIJKEN
5. Priv	ate Claims						
					2 6 5		3
					3	<del></del>	
Mic	hael Mileski		, September 94		4 - 7 - 8	b1	101112
l	Tabl Wilcon	, in a field survey on			5		
do hereb	y certify that under re	equirements of P.A. 74, Michigan P.	A. of 1970, the corner points mer	ntioned	6 10 17		
		in conformance with regulations a	•		,		
		tructions of the United States Depa faCourt of Law and/or that the com					
		vith the rules of the Michigan Board	•		8 19-20	) <del> 2</del> 1 <del>- </del> 2	2 23 24
		re-established, monumented, re			9		
expresse					10 30 29	28 2	7 26 25
NOTE:	Not more than 4	corners, all in the same town :	and range, may be recorde	d	11		
HOIL.	on this certificate		arra range, may be recovered		12 _ 1 3		
	on this oci inocit				13		
A. Des	cription of original	I monument and accessories a	nd/or subsequent restoration		13		<del></del>
•	•						
M-1	2; East One-Q	uarter Corner Section 36;					
	See back of	f form.					
							•
		•					
						•	
,							
B. Des	cription of corner	evidence found and/or method	applied in restoring or rees	stablishing c	corner:		
	•			_			
M-1	2; East One-qu	uarter Corner Section 36;					
						- ~	
		ow located in a flooded					
	accessories. Reestablished the east one-quarter corner of section 36 midway and on line between						
	the southea	ast corner of section 36 a	nd the northeast corne	er of section	on 36.		
1.		Coordinates		ne Coordin			•
	For E¼ Cor			ss Corner		•	
	Grid Systen	n - <b>NAD 83</b>	Grid Syste	em - NAC	83		
	Zone Numb	er - 2111 Michigan North	ı Zone Num	nber - 211	1 Michigan	n North	
	Units	<ul> <li>International Feet</li> </ul>	Units	- Inter	rnational Fo	eet	
	Υ	= 567909.54242	Υ	= 56	8226,477	03	
	Χ	= 26154302.57443	×	<b>= 26</b>	154305.8	7655	
C. Des	crintian of manum	ent for corner and accessories	established to pernetuate	locating the	position of th	ne corner:	
0. 500	onpaon or monum	ent to: control and accordance	obtainer to purpose		<b>P</b> • • • • • • • • • • • • • • • • • • •		
M-1	2: East One-go	uarter Corner Section 36;	203008206964				
		•	AE MICH	<sup>ra</sup> les.			
	See back o	f form.	A A Part of the second of the	r v			
			MICHAEL D.	<b>*</b> * *			
			### MILESKI	\* <b>\</b>		•	
			PROFESSIONAL	a K			
			SURVEYOR	<b>∤</b> ♀ቜ			
			No.	10 M			
			39091	N. F			
			Alexander Alexander	2.00			
			TE SSION OF	•			
	11.	:110	ः चयानु <b>ष्यक्र</b> ाहुगान्त्र स		. ~		
Signed t	Orlow YOU	taller rear	<u>حـــــ</u> Date	15	$\nu_{\circ}$	1000	

39091

Surveyor's Michigan License No. ...