LAND CORNER RECORDATION CERTIFICATE

Transfer in the first

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	MARQUETTE
1. PUBLIC LAND SURVEY	T. 46 N. R. 25 E.		Co.
	N. E.		
	N. R. W. W. S. R. W.		
3. MISCELLANEOUS PROPERTY IN SECTION	_ ,T S., R W.		
4. LOT NO, REC	ORDED PLAT		
S. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
restored as expressed below of survey instructions of the court of law. Furthermore	in lines 1 and 2 above (ide 24 19 76, establishe and in conformance with reg United States Department of e, that the corner points not found, recovered, restored, ne Michigan State Board of I bonument and accessories and Wood Post. Y. birch (idea)	entified with circles on indexed, re-established, monumented ulations and rules therefore a fithe Interior, Bureau of Landmentioned in lines 3,4 and 5 established or re-established Registration for Land Surveyor of Subsequent restoration: 6 - 835 W - 21 1ks.	P.A. 74, Michigan P.A. of 1970, code diagram — over) were, in a ed, re-monumented, recovered or s required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in consess or, by a Decree of a Court of
N.W. Section corner;	i. biren) - 532 E - 11 1RB.	
Nothing found.			
B. Description of corner evidence at record distance	dence found and/or method s	applied in restoring or re-esta	blishing corner: 35 and 36 - T46N - R25W.
		•	
		. N	caring the position of the corner:
C. Description of monumen 1" pipe, 4" aluminum		s established to perpendice to	cating the position of the corner:
7" sugar maple S 38°E 7" sugar maple S 66°W	: - 21.40'		
D.N.R. Monument - wes	t - 9.24°		
D.N.R. Monument - wes	t - 9.24°		
D.N.R. Monument - wes	t - 9.24°		
	t - 9.24°	DATE	
SIGNED BY	t - 9.24°		(SEAL)
SIGNED BY	registration no.		(SEAL)
SIGNED BYSURVEYOR'S MICHIGAN I	registration no.		(SEAL)