MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_46 NR_25_W__

			Marquette COUNTY
DESCRIPTION	OF	CORNER	section Corner common to Sections 8,9,16,17
DESCRIPTION	OF	CORNER	MONUMENT_1" Pipe with A" Prass cap
WIT TNESSES	то	CORNER	_5" Spruce - N_70 F = 14 Idnks
			5" Spruce - N 80 W - 29 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while working in this area. Corner had been previously located and perpetuated by unknown. One original B.T. still in place, in poor condition.

Corner was placed and witnessed July 10, 1951.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 7/25/51