## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY
MICHIGAN
RECEIVED FOR RECORD

For corners in MARQUETTE	Located In:	Corner Code #	1999	DEC 22	AN II	: 25
(County)			0.		<i>r</i> ,	A 1
1. Public Land Survey	Public Land Survey T_46N R_25W		Patricia d. Mankey REGISTER OF DEEDS OF			
Property Controlling S. in Section S. Miscellaneous S. Property in Sec. S.	T R R T R R T R R R R R R R R R R R R R		Register of	∖lβER <b>F</b> Deeds Stan		
4. Lot No, Record	ded Plat					
5. Private Claims			A B C D	E F G	.3 ————————————————————————————————————	J K
I, <u>GERALD W. CARLSON</u> , in a field survey on <u>October 28th</u> , 19 99, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as			5 5 8-	9	10	-11
required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of		5 7 10 17	16-	15	14	
Land Surveyors or by a Decree of recovered, found as expressed below		ed, re-established, monumented,	9 19 20	21	-22	_23
NOTE: Not more than 2 corne on this certificate.	ers, all in the same town and	d range, may be recorded	10 30 29	28	27	26
A. Description of original monu		or subsequent restoration:	12 31 32	33	-34-	35-
1999: Not part of original surve	γ,		P.A. 345	BY PEER OF 1990	; GHC 2.	JUP
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:			-Zan	y 4 /	190	ioenic I
D-1: 1999: Corner position esta Northwest and Northeast corner Section 32, T47N-R25W. Distar Northwest and Northeast corner	rs of Section 5, on line betw nces are 2635.64' West and	veen the Southwest corner of a d 2635.64' East along the Nor	Section 32 and the rth Township Line (	of T46N-R2	arter c 25W t	orner of
C. Description of monument for D-1: 1999: Set a 2 3/8" O.D.	or corner and accessories es aluminum pipe capped with	stablished to perpetuate locating a 3 1/4" diameter aluminum to	ng the position of t ablet Marquette Co	he corner: unty Surve	y Mor	nument

NOE,

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

2.2'

99100

GERALD W.
CARLSON
SURVEYOR
No.
24589

Signed by Gerold Walson

Surveyor's Michigan License No.\_\_

stamped to identify the corner. Monument is 0.25' above ground. Referenced by:

Corner Search Sheet

Green Steel Sign Post w/ Yellow Survey Marker Sign

T46N-R25W

Bk. 12, Pg. 132

Date 12-8-99