## SURVEY & REMONUMENTATION

APR 2 8 1995

## LAND CORNER RECORDATION CERTIFICATE COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD

1994 DEC 29 PM 1: 55


Fo	r corners in	i iiiig i ioquii	oment of Act 14, mon	
	Marquette (County)	Located In:	Corner Code ##	REGISTER OF DEFOS OF
1.	Public Land Survey	T R T R T R T R	I-12	P.A. 345 OF 1990  Xarry J. Bussel  DATE Sept 19, 1994
2.	Property Controlling in Section	S T R S T R		LIBER 1 PAGE 222
3.	Miscellaneous	S T R		Register of Deeds Stamp & File Number
	Property in Sec.	S T R		
4.	Lot No,	, Recorded Plat		A B C D E F G H ! J K L M
5.	Private Claims			

Michael Mileski September . 19 in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
  - I-12; West One-Quarter Corner Section 35;

See back of form.





- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- I-12; West One-Quarter Corner Section 35;

Found a 1" iron pipe projecting 16 inches above ground and within 3 feet of being midway and on line between the southwest corner of section 35 and the northwest corner of section 35.

## **State Plane Coordinates:**

Grid System - NAD 83

Zone Number - 2111 Michigan North

Units

- International Feet

= 567966.91412

Х = 26143755.94361

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - I-12; West One-Quarter Corner Section 35;

Replaced found 1" iron pipe with 2" I.D. x 30" aluminum pipe with 3" aluminum cap (Berntsen A1NB30) appropriately stamped as to location.

Set 60d spike Set 60d spike Set 60d spike Set 60d spike	W/side N/side S/side E/side	8" Jack Pine 10" Jack Pine 7" Jack Pine	N26°E S76°E N76°W	52.54' 16.08' 19.33'
Set oud spike	E/SIGE	10" Jack Pine Location Post	N28°W North	44.51' 1.5'
		Location 1 ost	1401 (11	1.5

All of the above ne	ew bearing trees mark	marked with upper and lower face blazes and scribed "NBT".		
igned by Windows	ishabill	Date 21 Nov 1994		
urveyor's Michigan License No	39091	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197		

A. Description of original monument and accessories and/or subsequent restoration:

1-12; West One-Quarter Corner Section 35;

6434 1

Originally established during U.S. Survey conducted by Wm. Ives, D.S. for Douglass Houghton, D.S. in 1845 and monumented with a wood post witnessed by a Spruce Pine 7 S74°E 17 lks. and a Spruce Pine 7 N63°W 54 lks.

2.1 | 1 1 1

This corner was remonumented with a jack pine post by the Marquette County Road Commission on 27 May 1942 at a position intended to be midway and on line between the southwest corner of section 35 and the northwest corner of section 35. The M.C.R.C. did not note any new bearing trees. The Marquette County Road Commission intended to reestablish all U.S. corners lying between the southwest corner of section 35 and the northeast corner of section 27 on line between these two corners at equally spaced intervals. Refer to M.C.R.C. field book 717.