## STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

## LAND CORNER RECORD

			Marquette	(	COUNTY
		T _	46 N	R	26 W
DESCRIPTION OF CORNER	Section corner for sections $\frac{20}{20}$	0/21 9/28			<del></del>
CORNER MONUMENT	1" pipe with 4" aluminum cap				
DATE MONUMENT PLACED AND WITNESSED 10/22/70					
WITNESSES TO CORNER 7" J. Pine (S 20) (NBT) N 53° W, 46.5'					
N	12" J. Pine (NBT) North, 1.1	<u> </u>			
	AND				
CIRCLE CORNER REGISTERED					

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set by single proportionate measurement N and S between Escanaba River south and line tree north. Departure was determined from occupation to east. Old blaze line N and S and east. Other old blazes near-by. No evidence of original corner found.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68