## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

T 46 N R 26 W  DESCRIPTION OF CORNER Section corner for sections 19/20  1" pipe with 4" aluminum cap
DESCRIPTION OF CORNER Section corner for sections 19/20
CORNER MONIMENT 1" pipe with h" aluminum cap
CONTENT PONDIENT
DATE MONUMENT PLACED AND WITNESSED 11/6/70
WITNESSES TO CORNER 6" B. Spruce (S. 18) (NBT) N 4° W, 19.3'
7" B. Spruce (S. 20) (NBT) S 28° E, 8.2'
AND  CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set from swamp edges north, south and west. No evidence of original corner. No lines or occupation.

SURVEYOR'S SEAL

SIGN

REGISTERED LAND SURVEYOR

DATE .

11/23/70

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68