

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Marquette COUNTY
46
T 45 N R 26 W

DESCRIPTION OF CORNER 1/4 corner for sections $\frac{33}{4}$ T46N R26W
 $\frac{4}{4}$ T45N R26W

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED November 4, 1970

WITNESSES TO CORNER..... 18" W. Pine, (1/4S) (NBT) S 73° E, 27.6'



4" B. Cherry, (1/4S) (NBT) S 14° W, 15.6'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set mid-point on line between section corners east and west. Checks well with Escanaba River east old blazes of what appears to be north and south line north and south of corner. No evidence of occupation.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Frank J. Bray
REGISTERED LAND SURVEYOR
Frank J. Bray

DATE

11/20/70

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68