

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD


Marquette COUNTY
46
T 45 N R 26 W

DESCRIPTION OF CORNER Section corner for sections $\frac{34}{35}$ T46N R26W
 $\frac{3}{2}$ T45N R26W

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED October 20, 1970

WITNESSES TO CORNER..... 6" J. Pine, (S.2) (NBT) S 27° E, 56.0'



18" J. Pine, (S.3) (NBT) S 54° W, 90.0'

AND _____

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two possible B.T.'s in proper distance and bearing.
Both stumps in poor condition.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED Frank J. Bray DATE 11/20/70
REGISTERED LAND SURVEYOR
Frank J. Bray

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68