## STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

## LAND CORNER RECORD

			Marquette	COUN	ΙΤΥ
		τ_	46 N	R <u>26</u>	<u>W</u>
DESCRIPTION OF CORNER	a corner for sections 20/21				
CORNER MONUMENT	1" pipe with 4" aluminum cap				
DATE MONUMENT PLACED AND WITNESSED 10/23/70					
WITNESSES TO CORNER 9" W. Birch ( ≤ S) (NBT) N 69° W, 7.51					
N 2 1	3" Balsam (½ S) (NBT) 57° E,	27.	31	. <u>.</u>	
	AND				
CIRCLE CORNER REGISTERED					

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set by proportionate measurement between section corners. No evidence of original corner found. Several old and new blazes in vicinity of corner.

SURVEYOR'S SEAL

SIGNED REGISTERED LAND SURVEYOR

DATE 11/20/70

DISTRIBUTION:

Frank J. Bray

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing

R 4047 Rev. 10/68