

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in  
**T Marquette**  
 (County)

|                                   | Located In: | Corner Code # |
|-----------------------------------|-------------|---------------|
| 1 Public Land Survey              | T 46N R 26W | J8            |
|                                   | T R         | K7            |
|                                   | T R         | K8            |
|                                   | T R         | M11           |
| 2 Property Controlling in Section | S T R       |               |
|                                   | S T R       |               |
| 3 Miscellaneous Property in Sec.  | S T R       |               |
|                                   | S T R       |               |

Register of Deeds Stamp & File Number

4 Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5 Private Claims \_\_\_\_\_

I, **Keith Sackett**, in a field survey on **July 31**, 19**90**, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, nonumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

|    | A  | B  | C  | D  | E  | F  | G  | H  | I  | J  | K  | L  | M  |
|----|----|----|----|----|----|----|----|----|----|----|----|----|----|
| 2  | 1  | 2  | 3  | 4  | 5  | 6  | 7  | 8  | 9  | 10 | 11 | 12 | 13 |
| 3  |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 4  |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 5  |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 6  | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 |
| 7  |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 8  | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 |
| 9  |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 10 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 |
| 11 |    |    |    |    |    |    |    |    |    |    |    |    |    |
| 12 | 53 | 54 | 55 | 56 | 57 | 58 | 59 | 60 | 61 | 62 | 63 | 64 | 65 |
| 13 |    |    |    |    |    |    |    |    |    |    |    |    |    |

A. Description of original monument and accessories and/or subsequent restoration:

| J8   | K7   | K8  | M11  |
|--|--|---|--|
| Not set on original survey nor subsequently, apparently. | Original monument and accessories not found. Found fence corner west and south. Possible BT white pine NE only big dead white pine around. | Original monument and accessories not found. Found fence corner Int. N.S.E. | Original monument and accessories not found. |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

| J8                                | K7                        | K8                        | M11                          |
|-----------------------------------|---------------------------|---------------------------|------------------------------|
| Established at Int. of 1/4 lines. | Restored at fence corner. | Restored at fence corner. | Restored midway and on line. |

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

| J8   | K7   | K8   | M11  |
|--|--|--|--|
| Set 1" ID x 32" iron pipe w/4" aluminum cap. | Set 1" ID x 32" iron pipe w/4" aluminum cap. | Set 1" ID x 32" iron pipe w/4" aluminum cap. | Set 1" ID x 32" iron pipe w/4" aluminum cap. |
| 6" maple S28E 4.4' 1/4s BT                   | 6" spruce S87E 2.1' s24 NBT                  | 7" maple N14W 7.1' 1/4s NBT                  | 9" v. pine S06W 17.4' s36 NBT                |
| 6" maple N32W 15.0' 1/4s BT                  | 7" spruce N79W 21.8' s14 NBT                 | 4" maple S24W 13.9' 1/4s NBT                 | 6" v. pine S50E 10.9' s31 NBT                |
| 5" maple S45W 27.3' 1/4s BT                  | 10" spruce S34W 37.9' s23 NBT                | 14" maple N68E 23.7' 1/4s NBT                | 14" v. pine N05E 44.7' s30 NBT               |
|  |  | 7" balsam squared N12E 4.6'                  |  |

Signed by Keith Sackett Date \_\_\_\_\_  
 Surveyor's Michigan License No 19006

