CONS. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 46 พ.ศ. 28ที

			Marquette		COUNTY
DESCRIPTION OF CORNER _	1/4 Corner between S	ecs. 17-18	; . .		
CORNER MONUMENT 1"Pi	pe with 4" Aluminum 0	ap			
DATE MONUMENT PLACED AN	D WITNESSED6/15/64	<u> </u>			
ITHESSES TO CORNER	8 Jack Pine 2S(1	BT) 156° N	25 Iks.		
N	9" Jack Pine	East	9 Lits.		
18	9" Jacl Pine	S12° W	23 Цся.	- 11 ALL L	
CIRCLE CORNER REGISTERED	AND				

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at Wood Post set by unknown Surveyor. Position checks with corners $\frac{1}{2}$ mile to Morth and South.

SURVEYOR'S SEAL

Billy & Buckler

SIGNED BILLIA O. BUCKLES

DATE 7/29/1964

REGISTERED LAND SURVEYOR