CONS. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

27 i

46

|                          | Marquette                              | COUNTY       |
|--------------------------|--|--------------|
| DESCRIPTION OF CORNER    | 1/4 Corner between Sections 29-30      |              |
| CORNER MONUMENT          | l" Pipe with 4" Aluminum Cap.          |              |
| DATE MONUMENT PLACED AND | WITNESSED 6/16/67                      |              |
| VITHESSES TO CORNER      | 9" Jack Pine (1/4 S NRT) NAOE 50.31    |              |
| N                        | 9" Jack Pine (1/4 S NBT) 1141°11 23.91 |              |
| 30                       |  |              |
|                          | AND                                    |              |
| CIRCLE CORNER REGISTERED |  | <del> </del> |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway and on line between two Section Corners.
No evidence of original Corners.

SURVEYOR'S SEAL

SIGNED Billy 1. Buckler DATE 10/25/67

REGISTERED LAND SURVEYOR